



Bobcat®

Flail Cutter

FC155-FC175

(Europe Only)

FC200

Service Manual

(FC155 Europe Only) S/N A01P00101 & Above

(FC175 Europe Only) S/N 467500101 & Above

(FC200) S/N 467300101 & Above

PDF



DOWNLOAD



ALPHABETICAL INDEX

BRUSH DEFLECTOR (EARLIER MODELS)	30-40-1
DAILY INSPECTION	10-20-1
DELIVERY REPORT	III
DRIVE BELTS	10-50-1
DRIVE BELTS	30-100-1
DRUM	30-50-1
FLAIL KNIVES	30-60-1
HYDRAULIC MOTOR	20-10-1
HYDRAULIC CONTROL VALVE (S/N A01P00143 & BELOW, S/N 467500163 & BELOW, S/N 467300196 & BELOW)	20-20-1
HYDRAULIC CONTROL VALVE (S/N A01P00144 & ABOVE, S/N 467500154 & ABOVE, S/N 467300197 & ABOVE)	20-21-1
HYDRAULIC SCHEMATIC	SPEC-20-1
IDENTIFICATION AND MACHINE SIGNS (DECALS)	IV
LINKAGE	30-80-1
LUBRICATION	10-30-1
MANUAL STORAGE LOCATION	III
REAR HATCH	10-40-1
ROLLER ASSEMBLY	30-20-1
RUBBER SKIRT	30-30-1
RUBBER STOP	30-70-1
SERIAL NUMBER LOCATION	III
SKID SHOE	30-10-1
SPECIFICATIONS	SPEC-10-1
TROUBLESHOOTING	10-10-1
WEAR STRIP	30-90-1

**ALPHABETICAL
INDEX**



Bobcat®

CONTENTS

**SAFETY AND
MAINTENANCE**

SERIAL NUMBER LOCATION	III
Attachment Serial Number	III
MANUAL STORAGE LOCATION	III
DELIVERY REPORT	III
IDENTIFICATION AND MACHINE SIGNS (DECALS)	IV
SAFETY AND MAINTENANCE	10-01
HYDRAULIC SYSTEM	20-01
MAIN FRAME	30-01
SPECIFICATIONS AND SCHEMATICS	SPEC-01

**HYDRAULIC
SYSTEM**

**MAIN
FRAME**

**SPECIFICATIONS
AND
SCHEMATICS**

**CALIFORNIA
PROPOSITION 65 WARNING**
Diesel engine exhaust and some of its constituents are known to the State of California to cause cancer, birth defects and other reproductive harm.



Thank you very much
for your reading.
Please click here
to get more information.