

568 and 578 Round Balers TM- All Inclusive



TECHNICAL MANUAL

Round Balers 568, 578

TM3300 08 JUL 10 (ENGLISH)



John Deere Agriculture
Printed by Belgreen



Table of contents

FOREWORD

Section 05 - SAFETY

Group 05 - Safety Information

Section 10 - GENERAL

Group 10 - Serial Numbers

Group 15 - Torques for Hardware

Group 20 - Lubrication

Section 40 - ELECTRICAL SYSTEM — REPAIR

Group 05 - Connectors

Group 10 - Sensors and Switches

Group 15 - Actuators

Group 30 - ELS (Manual Twine Control Switch)

Group 40 - ELC Plus Monitor (Electronic Tying Control)

Group 50 - BaleTrak and BaleTrak Plus Monitor

Section 50 - POWER TRAIN

Group 10 - Walterscheid Powerline

Group 15 - Shear Bolt System

Group 20 - Cam-Type Cut Out Clutch (S.N. —06XXXX)

Group 21 - Cam-Type Cut Out Clutch (S.N. 06XXXX—)

Group 25 - Gear Case (w/o Precutter)

Group 30 - Precutter Gear Case

Group 35 - Chain Tension

Group 40 - Sprocket Alignment

Section 60 - BRAKING SYSTEM — REPAIR

Group 05 - Air Brakes

Group 10 - Hydraulic Brakes

Group 15 - Brake Shoe and Drum

Section 70 - HYDRAULIC SYSTEM — REPAIR

Group 05 - General Information

Group 10 - Bale Density Control Valve

Group 15 - Hydraulic Cylinders

Group 40 - Precutter or MAXICUTMAXICUT is a trademark of Deere & Company Precutter Electro-Hydraulic Valve

Section 80 - MISCELLANEOUS

Group 05 - Wheel Hub Repair

Group 10 - Bale Shape Indicator

Group 15 - Tongue

Section 85A - LUBRICATION SYSTEM (S.N. —049999) — REPAIR

Group 05 - Drive Chain Lubrication

Section 85B - LUBRICATION SYSTEM (S.N. 050000—) — REPAIR

Group 05 - Drive Chain Lubrication

Section 100A - PICKUP REPAIR

Group 15 - 2.00 m (6 ft 7 in.) Pickup with Rotary Feeder and Precutter Device

Section 100B - PRECUTTER SYSTEM

Group 05 - Adjustment

Section 120 - BALE CHAMBER ROLLS

Group 20 - Rolls and Bearings

Section 130A - NET TYING

Group 15 - Repair

Section 130B - TWINE TYING

Group 10 - Repair (Single Arm Twine Tying)

Group 15 - Repair (Double Arm Twine Tying)

Section 211 - DIAGNOSTIC TROUBLE CODE FOR BALETRAK CONTROL

- Group 05 - Description
- Group E00X - Battery Voltage
- Group E20X - Twine Actuator M1
- Group E21X - Net Actuator M2
- Group E23X - Pickup Valve Y4
- Group E24X - Knife Valve Y3
- Group E25X - Reverser Valve Y2
- Group E31X - Gear Case RPM Sensor S6
- Group E32X - Twine Pulley Sensor S7/S8
- Group E40X - Net Switch S4
- Group E41X - Right Gate Switch S1
- Group E43X - Full-Size Bale Switch S3
- Group E60X - EPROM

Section 240 - ELECTRICAL SYSTEM

- Group 05 - General Information
- Group 06 - Test Equipment
- Group 10 - Electrical System Diagrams for Road Light
- Group 14 - Electrical Diagram / Battery Wiring Harness
- Group 15 - Electrical System / ELS (Manual Twine Control)
- Group 15A - Electrical Diagram / ELS
- Group 15B - Checking Twine Tying Function
- Group 20 - Electrical System / ELC (S.N. —029999)
- Group 20A - Electrical Diagram / ELC (S.N. —029999)
- Group 20B - Checking Twine/Net Tying Function
- Group 25 - Electrical System / ELC (S.N. 030000—)
- Group 25A - Electrical Diagram / ELC (S.N. 030000—)
- Group 30 - Electrical System / BaleTrak Control
- Group 30A - Electrical Diagram / BaleTrak Control
- Group 30B - Diagnostic Modes

Section 250A - LUBRICATION SYSTEM - OPERATION AND TESTS (S.N. —049999)

- Group 05 - Theory of Operation
- Group 10 - Component Location
- Group 15 - Troubleshooting
- Group 20 - Diagnostic and Test Procedure

Section 250B - LUBRICATION SYSTEM - OPERATION AND TESTS (S.N. 050000—)

- Group 05 - Theory of Operation
- Group 10 - Component Location

Section 260A - AIR BRAKE SYSTEM - OPERATION AND TESTS

- Group 05 - Safety
- Group 20 - Air Brake System - Description
- Group 25 - Air Brake System - Tests

Section 260B - HYDRAULIC BRAKE SYSTEM - OPERATION AND TESTS

- Group 20 - Hydraulic Brake System - Description
- Group 25 - Hydraulic Brake System - Tests

Section 270 - HYDRAULIC SYSTEM - OPERATION AND TESTS

- Group 05 - Safety
- Group 10 - General Information
- Group 20 - Bale Density / Gate Control - Description
- Group 21 - Bale Density / Gate Control - Troubleshooting
- Group 22 - Bale Density / Gate Control - Tests
- Group 30 - Pickup Lift System (Baler without Precutter)
- Group 35 - Pickup with Reversible Rotary Feeder

Group 40 - Precutter or MAXICUTMAXICUT is a trademark of Deere & Company Precutter Hydraulic System - Description

Group 41 - Precutter or MAXICUTMAXICUT is a trademark of Deere & Company Precutter Hydraulic System - Tests

Section 330A - NET TYING - OPERATION AND TESTS

Group 05 - Troubleshooting

Group 10 - Theory of Operation

Section 330B - TWINE TYING - OPERATION AND TESTS

Group 05 - Troubleshooting

Section 399 - SPECIAL TOOLS — DEALER-FABRICATED

Group 05 - Manufacturing the Tools



Thank you very much
for your reading.
Please click here
to get more information.